

Notice of Alteration Form



Client File No. : <b>181.10</b>	Environment Act Licence No. : <b>1142</b>
Legal name of the Licencee: Municipality of Ethelbert	
Name of the development: Municipality of Ethelbert Lagoon	
Category and Type of development per Classes of Development Regulation: Waste Treatment and Disposal <input type="button" value="v"/> <SELECT>	
Licencee Contact Person: Shawna Low, Administrative Assistant Mailing address of the Licencee: Box 115, 56 Second Ave. S. City: Ethelbert Province: MB Postal Code: R0L 0T0 Phone Number: (204) 742-3212 Fax: (204) 742-3642 Email: ethelbert@mymts.net	
Name of proponent contact person for purposes of the environmental assessment (e.g. consultant): Oswald Wohlgemut, JR Cousin Consultants	
Phone: (204) 489-0474 Fax: (204) 489-0487	Mailing address: 91 Scurfield Blvd, Winnipeg, MB R3Y 1M5
Email address: owohlgemut@jrcc.ca	
Short Description of Alteration (max 90 characters): cap and adhesive of pipe to ensure no water penetration, fill low spots with clay.	
Alteration fee attached: Yes: <input type="checkbox"/> No: <input checked="" type="checkbox"/>	
If No, please explain: small repair	
Date: 2021-10-20	Signature:  Printed name: Shawna Low
A complete Notice of Alteration (NoA) consists of the following components: <input checked="" type="checkbox"/> Cover letter <input checked="" type="checkbox"/> Notice of Alteration Form <input checked="" type="checkbox"/> 2 hard copies and 1 electronic copy of the NoA detailed report (see " <a href="#">Information Bulletin - Alteration to Developments with Environment Act Licences</a> ") <input type="checkbox"/> \$500 Application fee, if applicable (Cheque, payable to the Minister of Finance)	<b>Submit the complete NoA to:</b> Director Environmental Approvals Branch Manitoba Sustainable Development 1007 Century Street Winnipeg, Manitoba R3H 0W4 <b>For more information:</b> Phone: (204) 945-8321 Fax: (204) 945-5229 <a href="http://www.gov.mb.ca/sd/eal">http://www.gov.mb.ca/sd/eal</a>
<b>Note: Per Section 14(3) of the Environment Act, Major Notices of Alteration must be filed through submission of an <a href="#">Environment Act Proposal Form</a> (see "<a href="#">Information Bulletin - Environment Act Proposal Report Guidelines</a>")</b>	



56 Second Avenue S., Box 115, Ethelbert, MB. R0L0T0 Phone: 204-742-3212, Fax: 204-742-3642 E-mail:  
methelbert@inetlink.ca

---

October 22, 2021

Director  
Environmental Approvals Branch  
Manitoba Sustainable Development  
1007 Century St.  
Winnipeg, MB  
R3H 0W4

To Whom It May Concern;

Please find attached the Notice of Alteration Form and all required documentation in respect to attached Inspection Report for the Ethelbert Lagoon, dated October 16, 2020.

On October 9, 2020 the Municipal Water Supervisor observed a potential leak of cell #2 at the lagoon and reported it to the Environmental Officer, Dave Yunker. Mr. Yunker conducted a lagoon inspection and concluded that a Director's Order would be issued and the Municipality would need to have an Engineering Assessment conducted. On October 19, 2020, Mr. Yunker advised the Municipality that his superiors would not approve the Director's Order and it would not be issued, however an assessment was still necessary. The Municipality contacted Manitoba Water Services Board and secured cost share funding and JR Cousin Consulting was hired to conduct the inspection.

JR Cousin Consulting conducted their inspection this spring and released the report with their observations and recommendations, attached.

The Municipality of Ethelbert would like to conduct the repair to the abandoned pipe by way of capping with adhesive as suggested by Mr. Wohlgemut, Environmental Scientist from JR Cousin. We feel this will satisfactorily alleviate the issue of leakage. In addition, we will pack and fill any low lying areas with clay to alleviate any standing water issues going forward. With approval, we are hoping to have this work conducted as soon as possible and before we get too deep into winter.

Should you require anything further, please call me at your earliest convenience; I may be reached at [ethelbert@mymts.net](mailto:ethelbert@mymts.net), office 204-742-3212 or by cell 204-648-3284. Many thanks for your attention herein.

Sincerely,

  
Shawna Low  
Administrative Assistant

June 23, 2021

700\708\708.02\02\Ethelbert Lagoon Assessment Report.docx

Mr. Ranveer Katyal, M.A.Sc.  
Water Services Branch  
Department of Central Services  
Unit 1A - 2010 Currie Blvd.  
Brandon, Manitoba  
R7B 4E7

**Via email**

**P&R 8.390 JRCC**

**E-708.02**

Dear Mr. Katyal,

**RE: Ethelbert Lagoon Dike Assessment Letter Report**

JR Cousin Consultants Ltd. (JRCC) has completed this letter report assessing the Ethelbert wastewater treatment lagoon dike condition in response to an inspection conducted by Manitoba Conservation and Climate in October 2020.

## **1.0 BACKGROUND AND SCOPE**

The Ethelbert wastewater treatment lagoon was constructed in 1966 as a two-cell facultative lagoon. The lagoon was licensed in 1968 by The Provincial Sanitary Control Commission under the Pollution of Water Prevention Act. It is currently operating under the Clean Environment Commission Order 1142, which was issued in 1988. The Municipality indicated that no record drawings of the earthen lagoon construction were produced and no geotechnical investigation has been conducted on the lagoon dikes.

The lagoon is located at SW 32-29-21 WPM, approximately 380 m southeast of the community of Ethelbert. The lagoon is surrounded to the south, west and north with forest land and to the east is agricultural land used for crop production. The forested area to the north also consists of low lying swamp areas, while the forested area to the south contains some low lying streams and swampy areas. The Fork River Drain (Fifth Order Provincial Drain) is located approximately 130 m south of the existing lagoon cells and is used for the existing lagoon effluent discharge.

The lagoon operator noticed a potential issue with ponding water outside of the lagoon cell in 2020 and contacted Manitoba Conservation and Climate. The Environmental Compliance and Enforcement branch conducted an inspection of the Ethelbert wastewater treatment lagoon in October 2020 and a leak was detected at the base of the south dike (storage cell). The enforcement representative requested an engineering assessment of the lagoon leak and a Notice of Alteration if repair works are necessary.

## **2.0 EXISTING LAGOON DIKE GEOTECHNICAL ASSESSMENT**

### **2.1 Background Information**

JRCC completed a geotechnical investigation of the potential expansion area to the southwest of the Ethelbert wastewater treatment lagoon in October 2015. A total of seven test holes were excavated across the site to determine the suitability of the soils for use as a clay lagoon liner or a potential borrow site. The test holes indicated that the soils consisted of medium and high plastic clay with sand and silt to a depth of 5.0 m below grade. Bedrock was not encountered, but water infiltration

was observed in all of the test holes at depths ranging from 1.4 m to 2.5 m below the surface. Laboratory testing indicated that these soils would likely be suitable for use as a re-worked and compacted lagoon liner, meeting provincial requirements for permeability. Any sand seams encountered would not be suitable for construction of a lagoon liner.

## 2.2 Dike Investigation

A soils investigation of the existing lagoon dike, near the area of concern on the south dike of the storage cell, was conducted on June 1, 2021. The soils investigation was to determine the suitability of the soils in the dikes to form a liner meeting provincial requirements, and if there were any indications of a leak from the lagoon cell. Five test holes were drilled in the south dike, with two test holes located in the center of the dike and three located on the inner slope (see test hole location plan attached). The depth of the test holes varied between 3.0 m and 4.5 m below the top of dike, and the observed soil profile in each hole was recorded (see attached test hole logs).

The soil profile through the centre of the dike consisted of surficial sand, followed by a layer of medium plastic sandy clay to a depth of approximately 2.0 m below the top of dike. Underlying this is a layer of wet sand to a depth of approximately 3.0 m, followed by a layer of sandy clay. Groundwater was infiltrating through the sand layer at a depth of 2.0 m to 3.0 m below the top of dike.

The soil profile through the inner slope of the dike consisted of high plastic organic clay from the surface to a depth of 1.7 m, followed by a layer saturated sand and sandy clay. Groundwater was infiltrating through the sand layer at a depth of 1.7 m to 2.5 m below the surface.

The investigation occurred after the storage cell had been drained, to expose the inner slope of the storage cell. No significant erosion was observed along the inner slope of the south dike. However, an additional abandoned drainage pipe was located through the dike that the operator was unaware of. This pipe was located at a depth of approximately 1.5 m below the top of dike, near the location of the existing cell drainage pipe. Both ends of the pipe were observed and the pipe appeared to go through the dike at an angle, along with a second pipe observed sitting on top of the first pipe on the outer dike slope (see location plan). There was evidence of moist conditions near the exit of this additional pipe on the outer slope, however as the pipe was no longer submerged in liquid due to the cell being drained, there was no liquid actively draining from the pipe. Photos of the abandoned pipes have been attached.

## 2.3 Laboratory Results

The laboratory analysis was conducted to confirm the suitability of the soil layer along the inner slope of the lagoon cell, for use as a cell liner. A sample from the high plastic organic clay along the inner slope liner was submitted to Wood Environment and Infrastructure Laboratories for particle size analysis and Atterberg limits. The Wood Environment and Infrastructure laboratory report has been attached. In general, soils that meet the following parameters would be suitable for use as a cell liner, meeting a provincial permeability requirement of  $1 \times 10^{-7}$  cm/sec or less:

- Liquid limit of 30% or greater
- 30% or more passing a number 200 mesh sieve
- Plastic index of 10% or greater
- 20% or more of clay particles.

The laboratory results indicated that the soil is a high plastic clay material and met the above requirements for cell liner suitability.

### 3.0 RECOMMENDATIONS AND CONCLUDING REMARKS

From a review of the field observations and the laboratory results, it is likely that the storage cell was constructed with a liner of high plastic clay located along the inner slope of the cell which meets provincial permeability requirements and has a thickness greater than 1.0 m.

The source of the ponding liquid observed by Manitoba Conservation and Climate is unknown, as testing on this liquid has not been conducted. It is possible that this liquid is effluent permeating through the lagoon dike, or it is possible that this liquid is from a groundwater source, as a layer of saturated sandy soils was observed at a depth of approximately 2.0 m below the top of the dike.

If the ponding liquid observed outside of the south dike was lagoon effluent, then it is likely that the source of the leak was from the additional abandoned discharge pipes. The abandoned discharge pipes are likely creating a permeable channel through the dike and potentially releasing wastewater when the lagoon level reaches the pipe elevation, at a height of 1.5 m below the top of the dike, which is consistent with the operator's observations of the ponding.


It is recommended that the Municipality remove the potential source of a lagoon cell leak by removing the abandoned pipes. If the pipes are removed, the lagoon liner in the excavated dike would need to be restored with high plastic compacted clay soils. The Municipality can attempt to cap the discharge pipe on both ends, however this may not resolve the issue if the discharge pipe is damaged and effluent is permeating through the soils around the pipe. Therefore, pipe removal is recommended rather than pipe capping. The lagoon operator should make observations of the area of concern during the summer months while the lagoon storage cell fills up with effluent, to determine if the location of a leak can be further clarified.

A Notice of Alteration will need to be submitted to Manitoba Conservation and Climate describing the procedures for resolving the lagoon leakage issue prior to any earth works being conducted on the lagoon cell dike.

If you have any questions, please contact the undersigned.

Yours truly,

**JR Cousin Consultants Ltd.**

  
Oswald Wohlgemut, M.Sc.  
Environmental Scientist

Attach: Site Photos  
Test Hole Location Plan  
Test Hole Logs  
Particle Size Analysis, Wood Environment and Infrastructure



## **ATTACHMENTS**

Site Photos

Test Hole Location Plan

Test Hole Logs

Particle Size Analysis, Wood Environment and Infrastructure

## Site Photos

Photo 1: Abandoned discharge pipe on outer slope



Photo 2: Abandoned discharge pipes on outer slope





Test Hole Location Plan

Test Hole Logs



REV	DESCRIPTION	DATE	INITIALS

SCALE BAR										
0	10	20	30	40	50	60	70	80	90	100
METERS										

**PRELIMINARY**

**JRC** **JRC** **JRC**

**Engineering & Construction**

**CONSTRUCTORS** **ENGINEERS** **EXCELLENCE SINCE 1981**

**PROJECT DATA**

**CLIENT:** SACRAMENTO COUNTY WATER CONTROL DISTRICT

**PROJECT NAME:** TEST HOLE AND PIPING LOCATION PLAN

**SCALE:** 1:500

**DATE:** 02/28/21

**SHEET:** 28 OF 37

J. R. Cousin Consultants Ltd.  
TEST HOLE LOGS

SYMBOL INDEX



GW. : Well graded gravels and gravel sand mixtures, little or no fines



GP. : Poorly graded gravels, gravel - sand mixtures, little or no fines



GM. : Silty gravels, gravel-sand-silt mixtures



GC. : Clayey gravels, gravel-sand-clay mixtures



SW. : Well graded sands, gravelly sands, little or no fines



SP. : Poorly graded sands, or gravelly sands, little or no fines



SM. : Silty sands, sand-silt mixtures



SC. : Clayey sands, sand-clay mixtures



ML. : Inorganic silts and very fine sands, rock flour, silty or clayey fine sands, or clayey silts with slight plasticity



CL. : Inorganic clays of low plasticity, gravelly clays, sandy or silty clays, lean clays



OL. : Organic silts and organic silty clays of low plasticity



CI. : Inorganic clays of medium or intermediate plasticity



MH. : Inorganic silts, fine sandy or silty soils



CH. : Inorganic clays of high plasticity, fat clays



OH. : Organic clays of medium to high plasticity, organic silts



Pt. : Peat, humus, swamp soils with high organic contents



TOPSOIL

The soil logs are based upon objective data available to us at the time of forming our opinions. The soil logs indicate site specific soil characteristics and must not be generalized over larger areas due to the limited number of test holes as compared to that of an unlimited number of test holes. Every effort is made to evaluate the information by methods generally recognized. The soil logs represent our opinions. J. R. Cousin Consultants Ltd. cannot be responsible for actual site conditions proved to be materially at variance from our analysis or from the data generalization over untested areas.

# J. R. Cousin Consultants Ltd.

## TEST HOLE LOG SHEET

LOCATION : Ethelbert Lagoon South Dike

CODE: E-708.02

DATE : June 1, 2021



COORDINATES: 5708941N, 404115E

ELEVATION: 339.100m

PROJECT : Ethelbert Lagoon Dike Assessment

METHOD OF SAMPLING: Drill Rig

TEST HOLE # 1




GW



GP




GM



GC



SW



SP



SM



SC



ML



CL



OL



CI



MH



CH



OH



PT



Topsoil



Static Water Level

The soil logs are based upon objective data available to us at the time of forming our opinions. The soil logs indicate site specific soil characteristics and must not be generalized over larger areas do to the limited number of test holes as compared to that of a unlimited number of test holes. Every effort is made to evaluate the information by methods generally recognized. The soil represent our opinions. J.R. Cousin Consultants Ltd. cannot be responsible for actual site conditions proved to be materially at variance from our analysis or from the data generalization over untested areas.


# J. R. Cousin Consultants Ltd.



















## TEST HOLE LOG SHEET

LOCATION : Ethelbert Lagoon South Dike  
 COORDINATES: 5708941N, 404077E  
 PROJECT : Ethelbert Lagoon Dike Assessment

CODE: E-708.02  
 ELEVATION: 339.200m  
 METHOD OF SAMPLING: Drill Rig

DATE : June 1, 2021  
 TEST HOLE # 2



	
GW	GP
	
GM	GC
	
SW	SP
	
SM	SC
	
ML	CL
	
OL	CI
	
MH	CH
	
OH	PT
	
Topsoil	Static Water Level

The soil logs are based upon objective data available to us at the time of forming our opinions. The soil logs indicate site specific soil characteristics and must not be generalized over larger areas do to the limited number of test holes as compared to that of an unlimited number of test holes. Every effort is made to evaluate the information by methods generally recognized. The soil represent our opinions. J.R. Cousin Consultants Ltd. cannot be responsible for actual site conditions proved to be materially at variance from our analysis or from the data generalization over untested areas.


# J. R. Cousin Consultants Ltd.



















## TEST HOLE LOG SHEET

LOCATION : Ethelbert Lagoon South Dike  
 COORDINATES: 5708945N, 404078E  
 PROJECT : Ethelbert Lagoon Dike Assessment

CODE: E-708.02  
 ELEVATION: 338.900m  
 METHOD OF SAMPLING: Drill Rig

DATE : June 1, 2021  
 TEST HOLE # 3



 GW	 GP
 GM	 GC
 SW	 SP
 SM	 SC
 ML	 CL
 OL	 CI
 MH	 CH
 OH	 PT
 Topsoil	 Static Water Level

The soil logs are based upon objective data available to us at the time of forming our opinions. The soil logs indicate site specific soil characteristics and must not be generalized over larger areas do to the limited number of test holes as compared to that of a unlimited number of test holes. Every effort is made to evaluate the information by methods generally recognized. The soil represent our opinions. J.R. Cousin Consultants Ltd. cannot be responsible for actual site conditions proved to be materially at variance from our analysis or from the data generalization over untested areas.



# J. R. Cousin Consultants Ltd.

## TEST HOLE LOG SHEET

LOCATION : Ethelbert Lagoon South Dike  
 COORDINATES: 5708946N, 404064E  
 PROJECT : Ethelbert Lagoon Dike Assessment

CODE: E-708.02  
 ELEVATION: 338.900m  
 METHOD OF SAMPLING: Drill Rig

DATE : June 1, 2021  
 TEST HOLE # 4



The soil logs are based upon objective data available to us at the time of forming our opinions. The soil logs indicate site specific soil characteristics and must not be generalized over larger areas do to the limited number of test holes as compared to that of a unlimited number of test holes. Every effort is made to evaluate the information by methods generally recognized. The soil represent our opinions. J.R. Cousin Consultants Ltd. cannot be responsible for actual site conditions proved to be materially at variance from our analysis or from the data generalization over untested areas.


# J. R. Cousin Consultants Ltd.

## TEST HOLE LOG SHEET

LOCATION : Ethelbert Lagoon South Dike  
 COORDINATES: 5708945N, 404066E  
 PROJECT : Ethelbert Lagoon Dike Assessment

CODE: E-708.02  
 ELEVATION: 338.900m  
 METHOD OF SAMPLING: Drill Rig

DATE : June 1, 2021  
 TEST HOLE # 5




GW



GP



GM



GC



SW



SP



SM



SC



ML



CL



OL



CI



MH



CH



OH



PT



Topsoil



Static Water Level

The soil logs are based upon objective data available to us at the time of forming our opinions. The soil logs indicate site specific soil characteristics and must not be generalized over larger areas do to the limited number of test holes as compared to that of a unlimited number of test holes. Every effort is made to evaluate the information by methods generally recognized. The soil represent our opinions. J.R. Cousin Consultants Ltd. cannot be responsible for actual site conditions proved to be materially at variance from our analysis or from the data generalization over untested areas.



## Particle Size Analysis, Wood Environment and Infrastructure


# PARTICLE SIZE ANALYSIS

Report Date: 18 June 2021

**Client**  
**Name:** JR Cousin Consulting Ltd.  
**Address:**  
**Attention:**  
**PO Number:**

**Project**  
**Name:** Ethelbert Lagoon  
**Address:**  
**Project No.:** WX11334.4100  
**Manager:** JW

**Gradation Specification:**



COBBLES	GRAVEL		SAND			SILT OR CLAY
	coarse	fine	coarse	medium	fine	

Sample ID	mUSCS	MC	D100	D60	D30	D10	LL	PL	% Gravel	% Sand	% Fines
● TH3 2021, 0.3 m	Cl	35.9	4.8	0.1			46	17	0	34	26 (Silt) : 40 (Clay)

WX11334.4100 - EVERGREEN WDG EXPANSION.GPJ 21/06/18 08:49 AM (WOOD - PSA MULTI RESULT WITH ATTERBERG)