



Photoplate 1 - View south on pipeline route in NW 17-10-28 WPM.



Photoplate 2 - View north on pipeline route in NW 17-10-28 WPM.



Photoplate 3 - View north on pipeline route in NW 17-10-28 WPM.



Photoplate 4 - View south on pipeline route across drainage next to low area in NW 17-10-28 WPM.



Photoplate 5 - View north on pipeline route at 1/4 line in NW 17-10-28 WPM.



Photoplate 7 - View northeast at 1/4 line on pipeline route into SE 17-10-28 WPM.



Photoplate 8 - View southwest at 1/4 line on pipeline route into SW 17-10-28 WPM.



Photoplate 9 - View north at bottom of Section into SW 17-10-28 WPM on pipeline route.



Photoplate 11 - View north at south side tree line in NE 07-10-28 WPM.



Photoplate 12 - View south on pipeline route in NE 0710-28 WPM.



Photoplate 13 - View south on pipeline route in NE 07 at existing A/R to Battery 09-07-10-28 WPM.



Photoplate 14 - View west up drainage crossing in SE 07-10-28 WPM.



Photoplate 15 - View north on pipeline route through drainage crossing in SE 07-10-28 WPM.



Photoplate 16 - View south on pipeline route south of drainage crossing in SE 07-10-28 WPM.



Photoplate 17 - View south on pipeline route in SE 07-10-28 WPM.



Photoplate 18 - View north on pipeline route in SE 07-10-28 WPM with drainage.





Photoplate 19 - View SW at deflection point in SE 07-10-28 WPM.



Photoplate 20 - View south at tree line adjacent to pipeline route at bottom of SE 07-10-28 WPM.



Photoplate 21 - View south toward tree line on pipeline route at bottom of SE 07-10-28 WPM.



Photoplate 22 - View NW along the pipeline route from the south boundary of SE 6-10-28 WPM.



Photoplate 39 - View south on pipeline route through NE 06-10-28 WPM.



Photoplate 41 - View south on route through shallow seasonal drainage in NE 06-10-28 WPM.



Photoplate 42 - View east up shallow drainage on pipeline route.



Photoplate 43 - View south at tree line at 1/4 line in E 1/2 06-10-28 WPM.



Photoplate 44 - View north on pipeline route at 1/4 line in NE 06-10-28 WPM.



Photoplate 23 - View south from north boundary of NE 31-10-28 WPM on pipeline route into NE 31.



Photoplate 24 - View south in NE 31-10-28 WPM on pipeline route through drainage crossing.



Photoplate 25 - View south over drainage crossing on pipeline route in NE 31-10-28 WPM.



Photoplate 26 - View up drainage crossing west of pipeline route in NE 31-10-28 WPM.



Photoplate 27 - View down drainage crossing east of pipeline route on NE 31-10-28 WPM.



Photoplate 28 - View north on pipeline route from bottom of 1/4 into NE 31-10-28 WPM.



Photoplate 29 - View SW at deflection point in SE 31-10-28 WPM.





Photoplate 30 - View south at second deflection point in SE 31-10-28 WPM.



Photoplate 32 - View north at bottom of 1/4 on pipeline route in SE 30-10-28 WPM.



Photoplate 33 - View west at Section line on pipeline route in NE 19-09-28 WPM.



Photoplate 34 - View east at Section line on route in NW 20-09-28 WPM. Bush has been pushed up.



Photoplate 35 - View west at deflection point on pipeline route in NW 20-09-28 WPM.



Photoplate 36 - View SE at deflection pt on pipeline route in NW 20-09-28 WPM.



Photoplate 37 - View SE at second deflection pt on pipeline route in NW 20-09-28 WPM.